

D888 System Update Ver.1.1.0 Release Note

Ver.1.1.0

This release is inclusive of previous updates.

- The tone quality of reverb is improved.
- The small crackling noise you may hear in the act of moving faders or pan/send/effect-return knobs is eliminated.

Ver.1.0.1

- The processing time becomes shorter when you move the location by using the counter, the FF or REW keys and the marks.
- A few low-level bugs are addressed.